



WINDING MACHINE	GM R100
Alimentation	Monophase 230 V 50/60 Hz
Pneumatic Alimentation	No
Absorbment	200÷750 W
Coil Internal Diameter	80÷300 mm (depends on the model)
Display	Numeric Viewer
Memory	No
Weight	40÷50 Kg
Dimensions	500x300x350 mm (LxPxH)

Functions of the Winding Macine GM R100

- Rewind previously cut threads quickly and easily
- The rewinder is available in 3 versions depending on the size of the coil to be obtained



VIDEO